



Customer and Market Operations  
EMEA Customer Care

Service Bulletin No. SB-002/10.01.08

RH-70

## SERVICE DEVICES, SPARE PARTS AND SWAP PACKAGES (LEVEL 2)

Version history:		
Version 7	10.01.08	Code for LCD shield changed (9590567 -> 9591580)
Version 6	16.01.07	Code for France and Ukraine SWAP packages removed. Codes for Nokia 1110i SWAP packages added for replacement.
Version 5	14.11.06	Code for E&A, Russia, South Africa and Turkey SWAP packages removed (not available anymore)
Version 4	23.02.06	Code for D-cover and type label removed. Not available as spare part for level 1. Code for LED and two connectors added
Version 3	15.09.05	ITEM number for fuse corrected (F100 -> F2000)
Version 2	22.08.05	Code for BB lid assy added
Version 1	25.07.05	Initial version

### Service devices:

PRODUCT	TYPE	CODE	NOTE
POS Flash Dongle (includes ACF-8 Universal Power Supply)	FLS-4S	-	Not available anymore
Universal Power Supply	ACF-8	0680032	
Service Data Cable	CA-28DS	0730319	
Data Service Cable (used with FLS-4)	CA-65DS	0730576	*
Opening Tool	SRT-6	0770431	
POS Flash Adapter	SF-10	0770748	
Soldering Jig	RJ-79	0780522	
Domesheet Assy Jig	SS-54	0780523	

\*) Optional flash concept, not needed with SF-10

There are no new service devices for RH-70 when compared with service devices for RH-64.



**Lead free rework must be used when repairing RH-70 phones.**

In addition to above-mentioned service devices, following enhancements are needed:

TYPE	DESCRIPTION
BL-5C	BATTERY PACK
ACP-12E (Euro)	AC TRAVEL CHARGER
ACP-12X (UK)	AC TRAVEL CHARGER
HS-7	HEADSET

More detailed information e.g. for flash concept can be found from Level 1 & 2 Service Manual on NOL.



Spare parts for RH-70:

Note: Components in following list marked with **bold text** are new components, which have not been used in other older phone models.

		CMO/EMEA CUSTOMER CARE SALO		
		( <b>LEVEL 2</b> ) SPARE PARTS LIST FOR		
		TRANSCIVER RH-70 NOKIA 1110		
ITEM	CODE	DESCRIPTION	UNIT	NOTE
I005	026376 2	ACOUSTIC CHANNEL ASSY	PC	
I007	026394 4	LIGHTGUIDE ASSEMBLY	PC	
<b>I010</b>	<b>026430 4</b>	<b>LID BB ASSY FOR P2493</b>	<b>PC</b>	
<b>I001</b>	<b>026807 9</b>	<b>A-COVER ASSY DARK BROWN CMG670</b>	<b>PC</b>	
<b>I021</b>	<b>026808 0</b>	<b>B-COVER ASSY DARK BROWN CMG670</b>	<b>PC</b>	
<b>I021</b>	<b>026808 1</b>	<b>B-COVER ASSY GREY CMG461</b>	<b>PC</b>	
<b>I021</b>	<b>026808 4</b>	<b>B-COVER ASSY BLUE CMG454</b>	<b>PC</b>	
<b>I001</b>	<b>026808 7</b>	<b>A-COVER ASSY GREY CMG461</b>	<b>PC</b>	
<b>I001</b>	<b>026809 0</b>	<b>A-COVER ASSY BLUE CMG454</b>	<b>PC</b>	
<b>I006</b>	<b>485092 1</b>	<b>LCD PM 96X68 FSTN BW MILOS</b>	<b>PC</b>	
V2400	486550 1	LED WHITE 90-335MCD 15MA 0DEG 1608	PC	
F2000	511904 5	SM FUSE FF 2A 32V 0402	PC	
I017	514029 1	BEETLE EMC MICROPHONE MOD -42DB	PC	
X2005	540925 5	SM LYNX BATT.CONN 3POL 12V 2A H7	PC	
H2400	546917 5	SM CONN BTB 2X5 F P0.5	PC	
I018	546947 3	CONN SYST TWIN JACK+FLASH CONN/4P	PC	
-	565023 9	ANTENNA MOD SAM EU	PC	
I003	638020 9	SCREW M1.8X6 DIN1654 TORX PLUS 19 MnB4	PC	
I011	959054 2	RF ASIC SHILD METAL	PC	
I012	959054	FEM SHIELD FOR P2572	PC	

☐ Level 1 ☒ Level 2 ☐ Level 3 ☐ Level 4

Version 7

# NOKIA

	4			
I004	959158 0	LCD SHIELD METAL P2493	PC	
I008	979544 2	DOMESHEET METAL PET	PC	
I002	979753 2	KEYMAT T9 LATIN SILVER	PC	
I002	979833 3	KEYMAT GREEK	PC	
I002	979833 6	KEYMAT ARABIC	PC	
I002	979833 8	KEYMAT HEBREW	PC	
I002	979834 1	KEYMAT CYRILLIC	PC	

**Note: When repairing RH-70 phones lead free rework method must be used.**



SWAP packages:

No SWAP packages available anymore for RH-70.

Nokia 1110i (RH-93) is the swap replacement. For N1110i SWAP codes please see corresponding RH-93 Service Bulletins.